

INFORMAÇÕES SOBRE A UTILIZAÇÃO SEGURA DE SVHC

INFORMAÇÕES RELATIVAS AO ARTIGO 33.º DO REGULAMENTO REACH SOBRE SUBSTÂNCIAS QUE SUSCITAM ELEVADA PREOCUPAÇÃO

Estimado(a) Cliente,

O Artigo 33º, parágrafo 1 do Regulamento REACH (Regulamento CE n.º 1907/2006) destina-se a possibilitar que os clientes de produtos fornecidos tomem medidas de gestão de riscos adequadas, que poderão ser necessárias devido à presença de Substâncias que Suscitam Elevada Preocupação (SVHC) nos artigos, indicadas na Lista de Substâncias Candidatas a Autorização atual, no sentido de garantir uma utilização segura.

De um modo geral, a FORD apoia os objetivos subjacentes do Regulamento REACH e especificamente o Artigo 33º, parágrafo 1, que são compatíveis com o nosso próprio compromisso em promover o fabrico, manuseamento e a utilização responsáveis dos nossos produtos.

Identificação de SVHC

Tanto quanto é do nosso conhecimento, com base nas informações recebidas da nossa cadeia de fornecimento e dos nossos dados de produtos, as SVHC presentes nos componentes dos artigos em quantidades superiores a 0,1% p/p são as indicadas na respetiva "Lista de SVHC" para a peça ou veículo específico.

Informações específicas sobre a utilização segura de artigos que contêm SVHC

Se aplicável, as informações específicas sobre a utilização segura de artigos que contêm SVHC será adicionada à respetiva "Lista de SVHC" da peça ou veículo específico.

Informações gerais sobre a utilização segura de artigos

Todos os veículos FORD são fornecidos com um manual do proprietário, que inclui informações sobre a utilização segura para os proprietários ou condutores dos veículos. As informações FORD sobre reparação e revisão dos veículos e das peças genuínas também incluem informações sobre a utilização segura para o pessoal de serviço.

Quando as SVHC indicadas na "Lista de SVHC" da respetiva peça ou veículo estiverem presentes, são incorporadas de forma a minimizar a eventual exposição aos clientes. O perigo para os seres humanos ou para o ambiente pode ser excluído, desde que o veículo e as respetivas peças sejam utilizados conforme previsto, e as reparações, revisões e manutenção sejam realizadas de acordo com as instruções técnicas para essas atividades e boas práticas da indústria.

Os veículos em fim de vida poderão ser eliminados de forma legal na União Europeia apenas em Instalações de Tratamento Autorizadas (ATF). As peças dos veículos devem ser eliminadas de acordo com as leis locais aplicáveis e orientações das autoridades locais.

Modelo: Ford Capri

Lista de SVHC com base na Lista Candidata da ECHA em 1 de janeiro de 2026

Informações específicas sobre a utilização segura de artigos que contêm SVHC

Não são necessárias informações específicas sobre a utilização segura. Devem ser cumpridas as informações gerais sobre a utilização segura de artigos.

Commodity	REACH SVHCs
Accessories	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
Body and Security Electronics	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	TBBA [79-94-7]
	Triphenyl-phosphate [115-86-6]
Body Covers and Ornamentation	Bumetrizole [3896-11-5]
Body Side Interior Trim (Hard Trim)	C,C'-azodi(formamide) [123-77-3]
Brakes	Lead [7439-92-1]
	TBBA [79-94-7]
Bumpers and Spoilers	Diocetyl tin dilaurate [3648-18-8]
	Lead [7439-92-1]
Climate	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
Closures and Lids BIW	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Lead [7439-92-1]
Closures and Lids Mechanisms	Lead [7439-92-1]
Coil Spring (Front, Rear)	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Console Floor/Rear	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
Cooling	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]

	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Boric acid [10043-35-3]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Driver Controls	Lead [7439-92-1]
EDS	1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4]
	Bumetrizole [3896-11-5]
	Decamethylcyclopentasiloxane [541-02-6]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
	Triphenyl-phosphate [115-86-6]
Electrified Drivetrain Systems	Lead [7439-92-1]
Exterior Lighting	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Fixed Glazing	Bumetrizole [3896-11-5]
Front / Rear Door Trim	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Hybrid Technology	Bumetrizole [3896-11-5]
	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
I/S Mirror	Lead [7439-92-1]
Interior Trim	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
IP Substrate and Ducts	Lead [7439-92-1]
Latches - Hood, Decklid and Liftgate Latches	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Latches - Side Door/Latch Mini Module	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Lead [7439-92-1]
Lower Body Structure	Lead [7439-92-1]
Mirrors	Cyclohexane-1,2-dicarboxylic anhydride [85-42-7]
	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
	TBBA [79-94-7]
Multimedia	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]

	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
Pedals	Lead [7439-92-1]
Power Supply	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	TBBA [79-94-7]
Powertrain Controls and Calibration	Lead [7439-92-1]
Powertrain Mounts	Lead [7439-92-1]
Restraint	Lead [7439-92-1]
Safety Electronics	Lead [7439-92-1]
Seating	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Seats - Foam - Cut and Sew	O,O,O-Triphenyl phosphorothioate [597-82-0]
	Triphenyl-phosphate [115-86-6]
Seats - Structures	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Shock Absorbers	Lead [7439-92-1]
Side Air Bag (SAB) and Curtain Air Bag (CAB)	Lead [7439-92-1]
Side Door Mechanisms	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Steering	Lead [7439-92-1]
	Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8]
Suspension Frames and Mountings	2-Methylimidazole [693-98-1]
	Bumetrizole [3896-11-5]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
Switches	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	4,4'-Isopropylidenediphenol [80-05-7]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Switches - General Use	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Upper Body Structure	Bumetrizole [3896-11-5]
Wash-Wipe	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
	TBBA [79-94-7]
Wheels Tires Jacks and Equipment	1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4]
	Lead [7439-92-1]

